



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 28, 2016

Mr. Brad Franklin
Government Relations Manager
Yamaha Motor Corporation, USA
6555 Katella Avenue
Cypress, CA 90630

NEF-150TB
16V-892

Subject: Speed Sensor Wire may Break

Dear Mr. Franklin:

This letter serves to acknowledge Yamaha Motor Corporation, USA's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

YAMAHA/XC155F/2015

Mfr's Report Date: December 8, 2016

NHTSA Campaign Number: 16V-892

Components:

ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 2,640

Problem Description:

Yamaha Motor Corporation, USA (Yamaha) is recalling certain model year 2015 XC155F SMAX scooters manufactured September 17, 2014, to October 27, 2015. The affected motorcycles may have an insufficiently clamped speed sensor lead wire, causing the wire to fatigue and break.

Consequence:

If the speed sensor wire breaks, the speedometer will not work, increasing the risk of a crash.

Remedy:

Yamaha will notify owners, and dealers will replace the speed sensor assembly, free of charge. The recall is expected to begin in January 2017. Owners may contact Yamaha customer service at 1-800-962-7926. Yamaha's number for this recall is 990111.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Yamaha's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement